

# VP2009PE V40 UK specific changes – 8<sup>th</sup> February 2012

(Should be read in conjunction with official V40 Change log)

Configuration	VP2009	status
1   Timezone set as 0, United Kingdom	√	Added on 23.40.23.2-YUK.rom
2   Web UI Logo connect to www.yealink.co.uk	√	Added on 23.40.23.2-YUK.rom
3   Auto provision : Check New Config : Power on+Repeatedly Interval(Minutes) : 1440 URL : http://prov.yealink.co.uk/1/ap/	√	Added on 23.40.23.2-YUK.rom
4   Add new Timezone : +4 United Arab Emirates (Dubai )	√	Added on 23.40.23.2-YUK.rom
5   Web UI add MWI option to subscribe to Voicemail or username, to voicemail by default (SubscribeMWIToVM = 1)	√	Added on 23.40.23.2-YUK.rom
6   VP2009: sipServer6.cfg VideoBandwidth the default value is 512	√	Added on 23.40.23.2-YUK.rom
7   VP2009 modify the key frames to 1s	√	Added on 23.40.23.2-YUK.rom
8   VP2009 modify the "xml body"format of the I frame synchronism.	√	Added on 23.40.23.2-YUK.rom
9   VP2009: WAN is set as User level accessable	√	Added on 23.40.23.2-YUK.rom
10   VP2009 /yealink/config/voip/sipAccount6.cfg中 audio codec prority: 1 PCMU 2 PCMA 3 G729 4 G722	√	Added on 23.40.23.2-YUK.rom
11   VP2009 MWI Subscription Period is set as 60	√	Added on 23.40.23.2-YUK.rom

Features		VP2009	Status
1	Added the IP dial feature when there is no account registered.	√	Added on 23.40.23.2-YUK.rom
2	VP2009 support delete the picture and video that system default.	√	Added on 23.40.23.2-YUK.rom
3	Added a option that can subscribe to account or voicemail	√	Added on 23.40.23.2-YUK.rom
4	VP2009 allow close browser feature	√	Added on 23.40.23.2-YUK.rom
BUG		VP2009	status
1	Fixed VP2009 DHCP option 66 autop failed issue	√	Added on 23.40.23.2-YUK.rom
2	Fixed VP2009 auto P failed after reset to factory issue	√	Added on 23.40.23.2-YUK.rom
3	Fixed VP2009 the video issue on AVAYA system	√	Added on 23.40.23.2-YUK.rom
4	Fixed VP2009 Website language display error and NTP server is empty issue	√	Added on 23.40.23.2-YUK.rom
5	Fixed VP2009 DHCP option 66 auto p couldn't release issue.	√	Added on 23.40.23.2-YUK.rom
6	Mailbox Light couldn't work in some occasion	√	Added on 23.40.23.2-YUK.rom